

Release Date: January 23, 2026

Firmware Version: V24.04.15

Database Version: V24.03.03

Bootloader Version: V01.04.04

Recommended Use

This release is recommended for all affected products listed below. It is important to keep your diagnostic tool current for optimum performance and to take advantage of all added enhancements. Please reference your user's manual on performing a software/firmware update on your diagnostic scan tool or code reader.

Affected Product(s)

- (0x0698) SDS43

New / Added Features & Functions

- New feature: Supports unlocking security for Ford vehicles via Wi-Fi
- New feature: Supports unlocking the Nissan Secure Gateway via the RSPro App
- Support 2024 Model Year Vehicles
- Support for upgrading the tool on macOS

Product Support

- Please visit us at innova.com/support for additional information