

Release Date: January 2026

Software Version: 2.6.4

Firmware Version: V24.03.02

Recommended Use

This release is recommended for all affected products listed below. It is important to keep your diagnostic tool current for optimum performance and to take advantage of all added enhancements. Please reference your user's manual on how to perform a software / firmware update on your diagnostic scan tool or code reader.

Affected Product(s)

- INNOVA® 7111 Smart Diagnostic System

New / Added Features & Functions

- Optimized OBD-II Diagnostics scan time for faster vehicle connection and data retrieval.
- Improved EV/HEV/PHEV Battery Health Live Data UI for better readability and overall usability, plus additional UI refinements.

Fixes / Updates

- **Bug Fixes:** Resolved various issues to enhance system stability and performance.

Product Support

Please visit us at pro.repairsolutions.com/Support for additional information.