

Release Date: December 2024

Software Version: V1.99.0

Firmware Version: V23.01.13

Recommended Use

This release is recommended for all affected products listed below. It is important to keep your diagnostic tool current for optimum performance and to take advantage of all added enhancements. Please reference your user's manual on how to perform a software / firmware update on your diagnostic scan tool or code reader.

Affected Product(s)

- **INNOVA® 7111 Smart Diagnostic System**

New / Added Features & Functions

- **Ford Security:** Updated the security unlocks for Ford to enable enhanced OEM functions, including Active Test, Special Functions, and Workshop Tool capabilities on Ford vehicles.
- **ECU Information:** Added a new feature to access and display detailed ECU information for better diagnostics and insights.
- **Active Test and Special Function for TCM System:** Enabled advanced Active Test and Special Function features for the Transmission Control Module (TCM) system.
- **User Interface Enhancements:** Redesigned and improved the user interface for a more intuitive and user-friendly experience.

Fixes / Updates

- **Bug Fixes:** Resolved various issues to enhance system stability and performance.

Product Support

Please visit us at innova.com/support or pro.repairsolutions.com/Support for additional information.